

DIN W75×H25mm Digital Graphic Panel Meter For Mosaic Panel


■ Features

- Various input function
: 0-2VDC, 0-10VDC, 1-5VDC,
DC0-1mA, DC4-20mA
- High/low-limit display scale function
- Max. display range: -999 to 9999
- Error display function
- High quality by microprocessor built-in
- Display accuracy: F.S. $\pm 0.2\%$ rdg ± 1 -digit



⚠ Please read "Safety Considerations" in operation manual before using.

■ Ordering Information



■ Specifications


| | | | | | |
|-------------------------|---|--|------------------|------------|----------|
| Model | M4V | | | | |
| Measurement function | DC voltage | | | DC current | |
| Measurement input | 0-2VDC \equiv | 1-5VDC \equiv | 0-10VDC \equiv | DC0-1mA | DC4-20mA |
| Max. allowable input | 110% of measurement input | | | | |
| Power supply | 12-24VDC \equiv | | | | |
| Allowable voltage range | 90 to 110% of rated voltage | | | | |
| Power consumption | Max. 2W | | | | |
| Display method | 7-segment LED display (red) (character height: 14mm) | | | | |
| Display accuracy | 0 to 50°C: F.S. $\pm 0.2\%$ rdg ± 1 -digit -10 to 0°C: F.S. $\pm 0.3\%$ rdg ± 1 -digit | | | | |
| Display cycle | 500ms | | | | |
| Setting type | Setting type with the front keys | | | | |
| Self-diagnosis function | Error display function | | | | |
| Insulation resistance | Over 100M Ω (at 500VDC megger) | | | | |
| Dielectric strength | 2,000VAC 50/60Hz for 1 min | | | | |
| Noise immunity | ± 300 V the square wave noise (pulse width: 1 μ s) by the noise simulator | | | | |
| Vibration | Mechanical | 0.75mm amplitude at frequency of 10 to 50Hz (for 1 min) in each X, Y, Z direction for 1 hour | | | |
| | Malfunction | 0.5mm amplitude at frequency of 10 to 50Hz (for 1 min) in each X, Y, Z direction for 10 min | | | |
| Shock | Mechanical | 300m/s ² (approx. 30G) in each X, Y, Z direction for 3 times | | | |
| | Malfunction | 100m/s ² (approx. 10G) in each X, Y, Z direction for 3 times | | | |
| Environ-ment | Ambient temperature | -10 to 50°C, storage: 20 to 60°C | | | |
| | Ambient humidity | 35 to 85%RH, storage: 35 to 85%RH | | | |
| Unit weight | Approx. 83g | | | | |

※Environment resistance is rated at no freezing or condensation.


Graphic Panel Meter

■ Dimensions

(unit: mm)



● Bracket



■ Input and Connection

| Input | Display | Connection |
|---------|----------|---|
| Voltage | 0-2VDC | 0-2VDC, 1-5VDC, 0-10VDC SOURCE HI ↓ LOW ↓ - + 1 2 3 4 5 6 |
| | 1-5VDC | |
| | 0-10VDC | |
| Current | DC0-1mA | DC0-1mA SOURCE HI ↓ LOW ↓ - + 1 2 3 4 5 6 |
| | DC4-20mA | DC4-20mA SOURCE HI ↓ LOW ↓ - + 1 2 3 4 5 6 |

■ Factory Defaults

| Parameter | Factory default | Parameter | Factory default |
|-----------|-----------------|-----------|-----------------|
| range | 0-2U | dot | 0.0 |
| L-5C | 0000 | in-b | 0000 |
| H-5C | 0.0 | LoC | OFF |

■ Error Display

Display indicates "Error" when wrong measuring input value is applied.

⊙ Display an Error


- In case of lower value than measuring input value.
E.g.) In case of applying DC2mA when measuring input range is selected as DC4-20mA: L L L L flashes.
- In case of higher value than measuring input value.
E.g.) In case of applying DC22mA when measuring input range is selected as DC4-20mA: H H H H flashes.
- In case of damaging the memory chip by high frequency noise, strong surge noise: E r - E flashes.

⊙ Cancellation of Error

- H H H H and L L L L Error is to exceed measuring input range, therefore if measuring input value is applied with in input range, Error message will be cleared automatically.
- 0 0 E r is indicated by mis-connection or in case of occurring something wrong in measuring input. Please cut off the power and then check measuring input.
- E r - E indicates data damage programmed in memory chip, and damaged data can not be recovered.
Ask a dealer shop for A/S.
It is impossible to clear E r - E by end-user, therefore it must be repaired by our engineer.

| | |
|-----|---|
| (A) | Photoelectric Sensors |
| (B) | Fiber Optic Sensors |
| (C) | Door/Area Sensors |
| (D) | Proximity Sensors |
| (E) | Pressure Sensors |
| (F) | Rotary Encoders |
| (G) | Connectors/ Connector Cables/ Sensor Distribution Boxes/Sockets |
| (H) | Temperature Controllers |
| (I) | SSRs / Power Controllers |
| (J) | Counters |
| (K) | Timers |
| (L) | Panel Meters |
| (M) | Tacho / Speed / Pulse Meters |
| (N) | Display Units |
| (O) | Sensor Controllers |
| (P) | Switching Mode Power Supplies |
| (Q) | Stepper Motors & Drivers & Controllers |
| (R) | Graphic/ Logic Panels |
| (S) | Field Network Devices |
| (T) | Software |

Parameter Description



How to change the setting value

1. When advance to MODE, change digit flashing by \leftarrow key then set DATA value by \rightarrow key.
2. After complete DATA value setting, please press \leftarrow key for 2 sec then it will move to next MODE saving DATA.
3. Press \rightarrow key for 2 sec to return RUN mode after changing (setting) DATA value in each MODE.

※Press \rightarrow key for 2 sec, then it will return to RUN without change setting value.


※When checking the setting value only in each mode. Press \leftarrow key for 2 sec, then press for 2 sec again.

(If press continuously, it will not advance to next mode and return to RUN mode)

※If any key is untouched for 60 sec, it will return to RUN mode.

High/Low-Limit Display Scale Function

This function is to display setting of particular high/low-limit value in order to display high/low-limit value of measuring input. If measuring inputs are a or b and display values are A or B, it will display a=A, b=B as below graph.




E.g.) Enables to set the display value for input as certain value (not "0") by using High/low-limit display scale function.

| Measuring input | Setting value | Display | Graph |
|-----------------|---------------------------------|-------------|-------|
| 0-10VDC | L-Scale: 0 H-Scale: 200 | 0 to 200 | ① |
| | L-Scale: 50 H-Scale: 200 | 50 to 200 | ② |
| | L-Scale: -100 H-Scale: 200 | -100 to 200 | ③ |
| | L-Scale: 200 H-Scale: -50 | 200 to -50 | ⑤ |

※ High/low-limit value setting range → L - 5ℓ (low limit): -999 to 9999, H - 5ℓ (high limit): -999 to 9999
But, there must be offset "1" between L - 5ℓ and H - 5ℓ.


Application Of Connections



Proper Usage

- Please read this catalog before purchase Panel meter.
- Power supply should be insulated and limited voltage/current or Class 2, SELV power supply device.
- Ambient condition
 - Please use this product under -10 to 50°C of ambient operating temperature and less than 35 to 85%RH of humidity. Moreover, use this item near normal temperature 20°C, the most important condition, which manages the accuracy.
 - Please avoid the condition of dew status by rapidly changing temperature.
 - Please avoid too much vibration or shock.
 - Please avoid the place where there are drag, dust, and chemical agent or gas, which is destructive to electrical parts.
 - Do not use this item where the voltage or noise is over the proper specification. it may cause malfunction.

- Storage
 - When you keep it, please avoid a direct ray of light and keep it under -20 to 60°C of ambient operating temperature and less than 35 to 85%RH of humidity. Wrap and keep it as initial state.
- Input Line
 - Shield wire must be used when the measuring input line is getting longer or there are too much noise.



| | |
|-----|---|
| (A) | Photoelectric Sensors |
| (B) | Fiber Optic Sensors |
| (C) | Door/Area Sensors |
| (D) | Proximity Sensors |
| (E) | Pressure Sensors |
| (F) | Rotary Encoders |
| (G) | Connectors/ Connector Cables/ Sensor Distribution Boxes/Sockets |
| (H) | Temperature Controllers |
| (I) | SSRs / Power Controllers |
| (J) | Counters |
| (K) | Timers |
| (L) | Panel Meters |
| (M) | Tacho / Speed / Pulse Meters |
| (N) | Display Units |
| (O) | Sensor Controllers |
| (P) | Switching Mode Power Supplies |
| (Q) | Stepper Motors & Drivers & Controllers |
| (R) | Graphic/ Logic Panels |
| (S) | Field Network Devices |
| (T) | Software |