



SWIV2.E337320
Relay Sockets and Assemblies - Component

[Page Bottom](#)

Relay Sockets and Assemblies - Component

[See General Information for Relay Sockets and Assemblies - Component](#)

AUTONICS CORP

E337320

18 Bansong-ro 513 beon-gil
Haeundae-gu
Busan, 612-070 REPUBLIC OF KOREA

Relay sockets, Cat. Nos. PG-08, -11, PS-08, -11, -08(N), -11(N).

Cat. No. PS-M8.

Marking: Company name and catalog designation on device or carton.

[Last Updated](#) on 2014-08-19

[Questions?](#)

[Print this page](#)

[Terms of Use](#)

[Page Top](#)

© 2015 UL LLC

When the UL Leaf Mark is on the product, or when the word "Environment" is included in the UL Mark, please search the [UL Environment database](#) for additional information regarding this product's certification.

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL's Follow-Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL's Follow-Up Service. Always look for the Mark on the product.

UL permits the reproduction of the material contained in the Online Certification Directory subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from the Online Certifications Directory with permission from UL" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "© 2015 UL LLC".